
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary ————————————————————————————————————									
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length		
S1028-027	Smoke	8/13/2008	ADS/TM	S11UU_015MH	Dry	Yes	548.25		



Smoke and Dye Testing Summary

High Level Sewershed

Run Summ Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Lengti
S1028-027	Smoke	8/13/2008	ADS/TM	S11UU_015MH	Dry	Yes	548.25
Isolated Pi Pipe ID	pes 	Upstream MH	Downstrea	Leng m MH (ft)		neter n)	
S11UU_(015G1	S11UU_015MH	S11UU_01	6MH 271.1	936	12	
S09UU_(001G1	S09UU_001MH	S11UU_01	5MH 277.0	607	12	

Observations & Photos

No smoke was observed during this test.